


Map 10.1 Potential Fish Passage Problems

 Road crossings
over fish bearing
streams

There are over 400 problem culverts within the Siuslaw Basin. Road stream crossings are meant to indicate potential problems for fish passage and do not represent actual culverts or the status of such culverts. Culvert data does exist for much of the Siuslaw but is not available for publication at this time.

Sources:
Road stream crossings
derived from 1:24,000
roads (BLM) and 1:24,000
streams (USFS).
Information derived by
ecotrust, 2001.

0 2 4 miles

Map scale = 1:350,000